




PB64

pull-link® Battery Tools Parts List

Model: PB64

Position in Drawing	Parts Descriptions	Art. Code	Quantities Each Tool
PB64 fig.B-17	Machine Screws	F60291H00	2
PB64 fig.A-12 or PB64 fig.B-23	Nosepiece K for P-link/Hemlok 6,4mm	L21601H00	1
PB64 fig.A-13 or PB64 fig.B-24	Nosepiece J for Monobolt 6,4mm	L21602H00	1
PB64 fig.A-14 or PB64 fig.B-25	Nosepiece H for P-link/Hemlok 4,8mm	L21603H00	1
PB64 fig.A-15 or PB64 fig.B-26	Nosepiece G for Monobolt 4,8mm	L21604H00	1
PB64 fig.A-1 or PB64 fig.B-1	Nosepiece F (6,4mm)	L21605H00	1
PB64 fig.A-11 or PB64 fig.B-27	Nosepiece E (6,0mm)	L21606H00	1
PB64 fig.A-10 or PB64 fig.B-28	Nosepiece D (4,8/5,0mm)	L40103H00	1
PB64 fig.A-9 or PB64 fig.B-29	Nosepiece C (4,0mm)	L40104H00	1
PB64 fig.B-3	Clamping Sleeve	L40109H00	1
PB64 fig.B-6	Push-pin Spring	L40111H00	1
PB64 fig.A-3	Hook	L40117H00	1
PB64 fig.A-6	Warning Light	L40120H00	1
PB64 fig.B-8	Flat Cross Head Screws	L40127H00	2
PB64 fig.B-21	Wrench	L40138H00	1
PB64 fig.B-9	Power Illustration	L40150H00	1
PB64 fig.B-10	Power Illustration Cable	L40151H00	1
PB64 fig.A-7	Trigger	L40607H00	1
PB64 fig.B-12	Mandrel Release Tube	L40705H00	1
PB64 fig.B-4	3-jaw Set for 6,4mm	Z20320H00	1
PB64 fig.A-2 or PB64 fig.B-2	Front Sleeve Set	Z40101H00	1
PB64 fig.A-16 or PB64 fig.B-22	3-jaw Set	Z40102H00	1
PB64 fig.A-4	Power Illustration Cover Set	Z40106H00	1
PB64 fig.A-8 or PB64 fig.B-18	Li-Ion Battery 14,4V 1,4Ah/4-cell	Z40122H00	1
PB64 fig.B-19	Li-Ion Battery 14,4V 2,8Ah/8-cell	Z40123H00	1
PB64 fig.B-20	Battery Charger Set	Z40124H00	1
PB64 fig.B-7	Spring Sleeve Set for 6,4mm	Z40206H00	1
PB64 fig.B-11	Tool Body Set pull-link PB64	Z40221H00	1
PB64 fig.A-5 or PB64 fig.B-13	Mandrel Collector	Z40351H00	1
PB64 fig.B-16	Motor	Z40358H00	1
PB64 fig.B-5	Push Pin Set	Z40401H00	1
PB64 fig.B-14	PCB Set	Z40403H00	1
PB64 fig.B-15	Gear Box Set	Z40404H00	1